

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

FR852
East
> 1
1.160 mi.
6127 ft.

NEPTUNE AVE
EAST 12TH STREET
BROOKLYN, NY

NY Spills S106008441
N/A

Site 1 of 3 in cluster FR

Relative:
Higher

SPILLS:

Actual:
11 ft.

Name: NEPTUNE AVE
Address: EAST 12TH STREET
City,State,Zip: BROOKLYN, NY
Spill Number/Closed Date: 0207368 / 2003-04-29
Facility ID: 0207368
Facility Type: ER
DER Facility ID: 68515
Site ID: 72619
DEC Region: 2
Spill Cause: Unknown
Spill Class: C4
SWIS: 2401
Spill Date: 2002-10-16
Investigator: KMFOLEY
Referred To: Not reported
Reported to Dept: 2002-10-16
CID: 196
Water Affected: Not reported
Spill Source: Unknown
Spill Notifier: Affected Persons
Cleanup Ceased: Not reported
Cleanup Meets Std: False
Last Inspection: Not reported
Recommended Penalty: False
UST Trust: False
Remediation Phase: 0
Date Entered In Computer: 2002-10-16
Spill Record Last Update: 2003-04-29
Spiller Name: Not reported
Spiller Company: UNKNOWN
Spiller Address: Not reported
Spiller Company: 999
Contact Name: KEVIN MCARDLE
DEC Memo: "Prior to Sept, 2004 data translation this spill Lead_DEC Field was FOLEY Con Ed e2mis #145585: 10-16-02 00:55HRS L. ZANZONICO (FOD) REPORTS, FOUND ONE QUART OF UNKNOWN OIL ON 400 GALLONS OF WATER IN MH 36476. AT THIS TIME OIL APPEARS TO BE CONTAINED AND NO SEWERS OR WATERWAYS WERE AFFECTED. OIL WAS DISCOVERED WHILE MARKING PHASES FOR 7B41. NO FIRE SMOKE OR PRIVATE PROPERTY WAS INVOLVED AND NO INJURIES WERE RELATED TO SPILL AND NO WEATHER CONDITIONS CONTRIBUTED TO HAZARD OF SPILL. NO OTHER OIL FILLED EQUIPMENT IN HOLE THAT APPEARS TO BE LEAKING. ENV STOP TAG# 22556 WAS PLACED AND UNABLE TO VERIFY IF ANY SEWER CONNECTIONS OR SUMPS IN STRUCTURE BECAUSE OF THE AMOUNT OF WATER. ONE LIQUID SAMPLE WAS TAKEN ON A E PRIORITY AND CLEANUP PENDING LAB SAMPLE. 10-16-02 01:21HRS CIG WAS NOTIFIED. 10-16-02 01:50HRS SAMPLE ARRIVED AT CHEM LAB. 10/16/02 0600HRS LAB RESULTS RETURNED <1PPM. UPDATE 10-16-02 1320 HRS D. WILLIAMS MECH B FLUSH DEPT REPORTS SHE DOUBLE WASH STRUCTURE WITH BIO-JEN 760 AND REMOVED ALL LIQUIDS FROM THE TOP OF THE STRUCTURE DUE TO D FAULT. SHE SUCKED UP OLD TAG AND PLACED NEW E.S.TAG #38116. WILL HAVE TO WAIT UNTILL FOD IDENTIFY AND TAG D-FAULT JOINT BEFORE JOB CAN BE COMPLETED 100 . UPDATE 10-16-02 1830 HRS DUE TO DEF SECONDARY (21) CABLE AND STRUCTURE MAKING WATER (WILL HAVE TO ORDER AND UNDER 50 PPM TANKER SILVER

Map ID
Direction
Distance
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number
EPA ID Number

BULLIT) AND THE AMOUNT OF WORK IN STRUCTURE THEY WILL BE UNABLE TO COMPLETE THIS CLEANUP WITHIN THE 24 HRS PROGRAM. AT 1832 HRS CALL CIG MCARDLE TO TAKE THIS OFF THE 24 HRS DEMINIMIS PROGRAM.

UPDATE***** 10-17-02 04:15HRS DOUBLE WASHED STRUCTURE WITH BIO GEN 760, TAG REMOVED AND NO SUMP FOUND. JOB 100 COMPLETED. S.PACE 49874. UPDATE 4/2/03 RECORDS SHOW THE D-FAULT WAS REPAIRED ON 10/17/02 E."

Remarks:

"1 QUART OF UNKNOWN OIL IN MANHOLD NUMBER 36476 - ON 400 GALLONS OF WATER. CON ED REF NUMBER 145585"

All Materials:

Site ID: 72619
Operable Unit ID: 858961
Operable Unit: 01
Material ID: 568650
Material Code: 9999
Material Name: other -
Case No.: Not reported
Material FA: Other
Quantity: 1.00
Units: G
Recovered: .00
Oxygenate: Not reported